OPERATION MANUAL

Thermohygrometer User's Manual



((

Model: 8723

INTRODUCTION

Thank you very much for purchasing this psychrometer with remote probe. The psychrometer is a micro processorbased design. Amust device for HVAC engineers use. No need to whirl the meter or refer to the chart. Easy to get the wet bulb and dew point quickly!

Features:

- Big LCD digital display
- Professional remote probe
- C& F selectable
- Handheld size, easy to carry
- · Low battery indication
- Fast response & Accurate reading
- Tripod mountable for long time use
- Dew Point calculated in seconds
- Wet Bulb calculated in seconds
- · Microprocessor circuitry for reliability
- Sleep and non-sleep selectable
- Powered by 4 AAA batteries
- Back light for dark places
 Self calibration function included
- HOLD/MIN/MAX function included

MATERIAL SUPPLIED

This package contains:

- √ The meter x 1
- ✓ Remote probe x1
- ✓ Battery x 4 (AAA size)
 - ✓ Operation manual x1
 - ✓ Hard carry case x1


Optional accessory:

✓ Calibration solution x2

LCD & KEYPAD

LCD DISPLAY





FUNCTION KEYS

1) key

- To turn on the meter with auto-sleep (20 minutes) and enter to normal mode
- Turn off the meter in any mode.

2) BKLT key

 Pressing the key to turn on the back light of LCD for 10 seconds.

3) C/F CAL+ Key

- In normal mode, pressing the key to switch the unit C and F.
- In calibration mode, pressing the key more than one second to stop the calibration manually.
- Pressing with on/off key at the same time to enter calibration mode.

4) **HOLD** key

- Only in normal mode, pressing the key to hold the current reading.
- Pressing the key again to unlock.

5) DP/WB key

Switching DP, WBT and air temperature in normal mode.

6) RST/MN/MX key

- Switching the display of min, max, and current value.
- Pressing more than one second to reset the min. and max. value.

7) On/Off + Hold key

- To turn on the meter without autosleep and enter to Normal mode.

POWER ON/OFF

- Pressing to turn on the meter with auto-sleep (20 minutes) and enter to normal mode
- Pressing to turn off the meter in any mode..

BACK LIGHT

-Pressing **"BKLT"** key to turn on the back light of LCD for 10 seconds.

UNIT SELECTION

 In normal mode, pressing "C/F CAL+" to switch the unit C and F.

HOLD READING

- Only in normal mode, pressing "HOLD" to hold the current reading.
- Pressing " HOLD " again to unlock.

AIR/DEW POINT/WET BULB

 Pressing **DP/WB** to switch AIR temperature, DP and WBT in normal mode.

CURRENT/MIN./MAX. VALUE

- Pressing RST owitch the display of current value, min. and max. value.
- Pressing RST MN/MX more than one second to reset the min, and max, value.

NON-SLEEP

CALIBRATION

- 1.To turn off the meter, plug the meter probe into 32.8% salt bottle and press "On/Off + F/C" key more than one second to turn on the meter and enter calibration mode.
- 2.You will see 3x.x% flashing on LCD (FIG.A), after 30 minutes, the flashing stop to indicate the "3x.x%" calibration is finished and saved. You can also manually end & save the calibration

4

by pressing "F/C CAL+" key for more than one second.(Note a)

- 3.Move the meter probe into 75.3% salt bottle and pressing "MN/MX/RST" more than one second to enter 7x.x% calibration. "7x.x%" will flashing on LCD.
- 4.Flashing stop after 30 minutes, up to now the whole calibration has been completed, you can also manually end and savethe calibration by pressing "F/C CAL+" key for more than one second. (Note d)

Note:

- a)You can manually exit calibration
 w/o saving by pressing "On/Off "key.
- b)Auto power off is automatically disable during calibration procedure.
- c)In order to get high accuracy, you must do the calibration at a 23±2 degree C & steady airflowroom.
- d)While the procedure is just finished, if the value differ from 7x.x% or 3x.x% for more than 0.3%, it means the calibration fail.(see trouble shooting 3)



TROUBLESHOOTING

- 1.Power on but no display.
- a)Make sure the time of pressing On/Off " key is more than 100 ms.
- b)Check the batteries are in place, good contact and correct polarity.
- c)Replace new batteries and try again.
- d)Move the batteries away for one minute and install again. 5

2.Display disappear.

- a)Check whether the low battery indicator displayed before display disappearred, if yes, replacing new batteries.
- b)Turn on the meter by pressing"On/Off + Hold" key to disable auto power off function for long time using.

3. Calibration failure.

- a)Check whether the low battery indicator displayed before calibration, if yes, replacing new batteries and try again.
- b)Make sure the good sealing when the meter probe plug into the salt bottle.
- c)Make sure the free air temperature is within 23±2 C and the airflow is stable.
- 4.E 11.
- a)RH calibration error. Need calibration again. **5.E 33.**
 - a)Circuit error in RH measurement channel. Returning the meter to the dealer.
 - 6.E 34.
 - a)Circuit error in Temperature measurement channel. Returning the meter to the dealer. Note: When the meter is on, plugging in the probe will also result in "E 33" or "E 34" in max. and min. mode.

SPECIFICATION

1. Range:

*Humidity measurement: 0~100%

*Temperature measurement: -10~60 °C (14 to140°F)

*DP :-73.4 to 59.9 $^{\circ}$ C (-100.0 to139.8 $^{\circ}$ F) *WBT: -13.4 to 59.9 $^{\circ}$ C (7.88 to 139.8 $^{\circ}$ F)

2.Accuracy:

*Humidity: ±3% from 10-90% (at calibration temperature); ±5% for others
*Temperature: ±0.6°C(±1°F)

3.Storage Temperature: -20°C to 60°C

4.Operating Temperature: -20°C to 60°C

Accuracy, the Zenith of Measuring / Testing Instruments!

Hygrometer / Psychrometer

Thermometer

Anemometer

Sound Level Meter

Air Flow meter

Infrared Thermometer

K type Thermometer

K.J.T. type Thermometer

K.J.T.R.S.E. type Thermometer

pH Meter

Conductivity Meter

T.D.S. Meter

D.O. Meter

Saccharimeter

Manometer

Tacho Meter

Lux / Light Meter

Moisture Meter

Data logger

Temp. / RH transmitter

Wireless Transmitter

More products available!

2005.11.1000