

Logger Selection Guide

Three easy steps to choose the logger you need!

Step1
Interface
you want?








Step2
Measured
parameters?



Step3
LCD display?



Final !

Bluetooth 	Temperature	LCD Display	88360
	Dual Temperature	LCD Display	88361
	Temperature + RH%	LCD Display	88362
	Temperature + RH% + Barometric Pressure	LCD Display	88363
USB 	Temperature	NO LCD Display	88181
	Temperature	LCD Display	88160
	Dual Temperature	LCD Display	88161
	Temperature + RH%	LCD Display	88162
	Temperature + RH% + Barometric Pressure	LCD Display	88163
SD Card 	Temp. + RH% + WBGT	LCD Display	87797
	Temp. + RH% + DP	LCD Display	87798
	Temp. + RH% + Probe	LCD Display	87799
USB Cable 	Temperature	NO LCD Display	88193
		LCD Display	88195
	Dual Temperature	NO LCD Display	88393/396
		LCD Display	88394/397/378
	Temp. + RH%	LCD Display	8808/88375
		LED Display	8809
Dual Temp. + RH%	LCD Display	88395/398	
USB Cradle 	Temperature	NO LCD Display	88128/13
		LCD Display	8828/14/15
	Dual Temperature	NO LCD Display	8833/335
		LCD Display	8834/345
	Temp. + RH%	LCD Display	8829
	Dual Temp. + RH%	LCD Display	8835/355